

January 7, 1941


FUEL LINE CHANGE

Aircraft Affected

All Luscombe aircraft equipped with fuel injectors, up to and including Serial no. 1659

All Luscombe aircraft Model 8A and 8B equipped with carburetors, Serial Numbers 1362 to 1658 inclusive.

Fuel line failures have occurred just aft of the firewall, which have led us to make a change at our factory, and to recommend that you make the same change on any and all subject aircraft in your possession immediately. The Civil Aeronautics Administration will require that our recommendation be complied with prior to annual relicensing, and that pertinent notations have been made in the log book. We illustrate the change by sketch below.



LUSCOMBE AIRPLANE CORPORATION
/s/ James G. Rising, Chief Engineer