


LUSCOMBE AIRPLANE CORPORATION

SERVICE BULLETIN NO. 5

February 27, 1939

TAIL TRAY REINFORCEMENT

The tail tray is a horizontal bulkhead located in the tail of the fuselage just under the horizontal stabilizer. In two or three instances owners have reported cracks in this tray just forward of its attachment to the rear bulkhead. The repair for such damage is shown on the sketch. It is recommended that you make the replacement shown on your airplane, whether or not cracks have yet developed.



Retyped March 2, 1960
SILVAIRE AIRCRAFT CO.
P.O. BOX 719
FORT COLLINS, COLORADO

ped